

HKS700E SERVICE LETTER

SL0801

Subject:

Extension of Time Between Overhauls (TBO)

Engine affected:

HKS700E from S/N 100600

Extension of the TBO:

HKS700E from S/N 100600 can increase the TBO from 800 hrs to 1000 hrs or 8 years period of operation.

Reason:

A program for extending TBO was carried out.

The TBO can be extended on account of the positive results of the examined engines.

Publications affected:

The amendments of Operations Manual will become effective with this Service Letter.

January 2009

HKS AVIATION CO.,LTD